Announcement: The drivers after August 2018 cannot be installed on some Windows 7 X64 Operation Systems

2021-11

After download and install this Security Update, new drivers will be installed successful.
Security Update for Windows 7 for x64-based Systems (KB3033929) :
https://www.microsoft.com/en-us/download/details.aspx?id=46148

Some 64-bit Windows7 Operation systems are unable to install the drivers after August 2018. Yellow exclamation point when viewing Device Manager:

The problem is caused by the unupdatedWindows7, or the Security Update is not installed.

Microsoft Security Advisory 3033929 :
<Availability of SHA−2 code signing support for Windows 7 and Windows Server 2008 R2: March 10, 2015>:
https://support.microsoft.com/en−us/help/3033929/microsoft−security−advisory−availability−of−sha−2−code−signing−support

From 2015, SHA-1 is a legacy cryptographic hash that is no longer secure, Microsoft is weeding out the SHA-1 certificate and migration to SHA-2, also to warn consumers about the risk of using a SHA-1 certificate. All digital certificates of drivers after August 2018, have been change to the SHA -2 (SHA256), resulting some un-updated Windows 7 could not recognize SHA-2 certificate.

Security Update for Windows 7 for x64-based Systems (KB3033929) :
https://www.microsoft.com/en-us/download/details.aspx?id=46148

After the Security Update is installed, 64-bit Windows 7 will directly install the new drivers successfully.

//

Windows 7 but not SP1 look at here:

Security Update (KB3033929) is used for Windows7 **SP1**(Service Pack 1), If your Operation System is Windows 7 only without SP1, it must be upgrade to Windows 7 SP1 first. Please Download and install *Windows 7 Service Pack 1 (KB976932)* : https://www.catalog.update.microsoft.com/Search.aspx?q=KB976932